

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L2	2	(erase or erasure) same overerase same (gate same stress)	USPAT	OR	OFF	2005/02/11 15:56
L3	2	overerase same (gate same stress)	USPAT	OR	OFF	2005/02/11 15:56
S1	0	(electrically same erasable) and (erase same pulse) and (erase same (verify or verifying) same (undererased or undererase or (under adj erased) or (under adj erase))) and (positive same gate same stress same reduce same positive same charge)	USPAT	OR	OFF	2005/02/09 15:25
S2	1	(electrically same erasable) and (erase same pulse) and (erase same (verify or verifying) same (undererased or undererase or (under adj erased) or (under adj erase))) and (positive same gate same stress)	USPAT	OR	OFF	2005/02/09 15:26
S3	0	(erase same pulse) and (erase same (verify or verifying) same (undererased or undererase or (under adj erased) or (under adj erase))) and (positive same gate same stress same reduce same positive same charge)	USPAT	OR	OFF	2005/02/09 15:27
S4	1	(erase same pulse) and (erase same (verify or verifying) same (undererased or undererase or (under adj erased) or (under adj erase))) and (positive same gate same stress)	USPAT	OR	OFF	2005/02/09 15:28
S5	1	(erase same (verify or verifying) same (undererased or undererase or (under adj erased) or (under adj erase))) and (positive same gate same stress)	USPAT	OR	OFF	2005/02/09 15:28
S6	1	(erase same (verify or verifying) same (undererased or undererase or (under adj erased) or (under adj erase))) and (positive same stress)	USPAT	OR	OFF	2005/02/09 15:34
S7	5	(erase same (verify or verifying) same (undererased or undererase or (under adj erased) or (under adj erase))) and (stress)	USPAT	OR	OFF	2005/02/09 15:52

S8	12	(erase same (verify or verifying)) and ((undererased or undererase or (under adj erased) or (under adj erase))) and (stress)	USPAT	OR	OFF	2005/02/09 15:54
S9	11	S8 not S5	USPAT	OR	OFF	2005/02/09 15:53
S10	7	S8 not S7	USPAT	OR	OFF	2005/02/09 15:53
S11	1	(erase same (verify or verifying)) and ((undererased or undererase or (under adj erased) or (under adj erase))) and (stress same positive)	USPAT	OR	OFF	2005/02/09 16:05
S12	1	"5359558".PN.	USPAT; USOCR	OR	OFF	2005/02/09 15:54
S13	1	"6331951".PN.	USPAT; USOCR	OR	OFF	2005/02/09 15:55
S14	1	"6438041".PN.	USPAT; USOCR	OR	OFF	2005/02/09 15:56
S15	1	"6493266".PN.	USPAT; USOCR	OR	OFF	2005/02/09 15:58
S16	1	"6717849".PN.	USPAT; USOCR	OR	OFF	2005/02/09 15:58
S17	51	erase and (positive same gate same stress) and (drain same source same ((bit adj lines) or bitlines))	USPAT	OR	OFF	2005/02/09 16:26
S18	22	S17 and substrate and (dielectric same layer)	USPAT	OR	OFF	2005/02/09 16:06
S19	15	erase and (positive same gate same stress) and (drain same source same ((bit adj lines) or bitlines) same ground)	USPAT	OR	OFF	2005/02/09 16:27
S20	9	S19 and substrate and (dielectric same layer)	USPAT	OR	OFF	2005/02/11 12:24
S21	0	(erase same postive same gate same stress) and ((ground or grounding) same source same drain same ((bit adj lines) or bitlines))	USPAT	OR	OFF	2005/02/11 12:35
S22	0	(erase same postive same gate same stress) and ((ground or grounding) same source same drain)	USPAT	OR	OFF	2005/02/11 12:35
S23	0	(erase same postive same gate same stress)	USPAT	OR	OFF	2005/02/11 12:35
S24	0	(postive same gate same stress)	USPAT	OR	OFF	2005/02/11 12:35
S25	5057	(gate same stress)	USPAT	OR	OFF	2005/02/11 12:35

S26	28	(erase same gate same stress) and ((ground or grounding) same source same drain same ((bit adj lines) or bitlines))	USPAT	OR	OFF	2005/02/11 15:51
-----	----	--	-------	----	-----	------------------